

Another Solution from



Repair the "Throw Away" driveshaft that GM supplied for the 1410 Series G3500 Express Van & Trucks. Yes!! We have a kit for that!!!



R996349 2003-2006 CHEVY G3500 EXPRESS MODELS
2003-2006 GMC G3500 SAVANNAH EXPRESS MODELS



The factory original driveshafts found on various 2003-2006 Chevrolet and GMC G3500 Express Models have a non-replaceable center support bearing. With the Rockford Kit you are able to cut the Original assemblies apart 1/4" below the friction weld and replace the Yoke and Center Support Bearing.

1500 11TH AVENUE ROCKFORD, ILLINOIS 61104
PHONE (815) 962-1411 FAX (815) 965-4857