

Feb 2014

*New High Speed CV Joints from*

**ROCKFORD**

*Now Available!!!*



*Rockford Driveline offers a money-saving solution with their High Speed CV Joint product line. Rockford reduces repair expense by enabling the user to simply change-out the defective CV joint, while maintaining the balance of the OEM high speed CV driveshaft. Rockford Driveline High Speed CV Joints come "fully loaded" and are produced to meet the*

*design requirements of the original equipment manufacturer. The new assembly includes Rockford's super-strength OE designed housing with precision-engineered internal components, as well as the new CV boot, end cap, grease, and hardware needed to do the job right.*

#### **450-80B (Front Shaft- Rear CV)**

2007-2011	Chevy Equinox (AWD)
2007-2011	Dodge Nitro (4x4)
2010-2011	GMC Terrain (AWD)
2008-2012	Jeep Liberty (4x4)
2007-2009	Pontiac Torrent (AWD)

MANUFACTURER & SUPPLIER OF DRIVELINE COMPONENTS  
1500 11TH AVENUE ROCKFORD, ILLINOIS 61104  
PHONE (815) 962-1411 FAX (815) 965-4857  
RockfordDriveLine.com