

Another Solution from

Mar. 2019

# **ROCKFORD**


## **DRIVE LINE**

Can we replace the "Staked-In" u-joint that Jeep used on the 2007-2018 Wrangler JK front shaft?  
Yes!! We have the parts to fix that!!!

*The factory original front driveshafts found on Jeep Wrangler JK models from 2007-2018 have a non-replaceable staked-in style u-joint. With the*



*Rockford Driveline parts below you are able to cut the Original assembly apart 1/8" below the friction weld and replace the Weld Yoke, Flange Yoke & U-Joint with a servicable 1310 system.*



**K153**

1310 Series  
U-Joint

**R2-2-1949**

Flange Yoke -  
2.558" Male Pilot  
3.750" Bolt Circle

**R2-28-12316**

Weld Yoke -  
3.281" CL to Weld  
2.504" Butt Dia.

**Call Today  
For Pricing**

THE SOLUTION COMPANY

"PROVIDING QUALITY, VALUE AND SERVICE FOR OVER 60 YEARS"

**RockfordDriveline.com | 815-962-1411**