

NOW AVAILABLE! HIGH SPEED CV JOINT 455-80



Rockford Driveline offers a money saving solution with our High Speed CV Joint product line. Our products reduce repair expense by enabling you to simply change out the defective CV joint, while maintaining the balance of the OEM high speed CV driveshaft. Rockford Driveline High Speed CV Jonits come "fully loaded" and are produced to meet the design requirements of the original equipment manufacturer. The new assembly includes Rockford's super strength OE designed housing with precision-engineered internal components, as well as the new CV boot, end cap, grease and hardware needed to do the job right.

455-80 - (Front CV)

2008-2011 Buick Enclave AWD 2009-2011 Chevrolet Traverse AWD 2007-2011 GMC Acadia AWD 2007-2010 Saturn Outlook AWD

455-80 - (Rear CV)

2009-2017 Nissan GT-R (One Piece Carbon Fiber Driveshaft)

This is a 100mm housing, accepts the 8mm bolts and fits onto 25 tooth shafts.

THE SOLUTION COMPANY